

Annual Inspection and Report

General Waste Permit # SW 620 2020 Annual Inspection of Landfill receiving CCR		
Inspection Date & Inspector	1/29/2021 Alan Phillips	
Is the landfill structure stable	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Comments: No visible erosion or instability. No slumping or cracking around slopes. Slopes were covered with snow at time of inspection.
2020 Volume of CCR Managed	290.91 yards	
Citizens Complaint Log Maintained	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Comments: No complaints in 2020
Employee Training Program Maintained	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Comments: Employee training log is kept in binder in the scale house. Employees were trained on 12/18/2020
Were any actions taken to manage fugitive dust?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Comments: Ash loads are covered with other waste as soon as practical and safe to do so.
Were any corrective measures taken during the last year?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Comments: None

PROFESSIONAL ENGINEER

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the State of Minnesota.

Print Name: William Keegan

Signature: 

Date 7/26/21 License # 41292



Photo 1 – Eastern and southern slopes of industrial cell B-1 as viewed from southeast corner, facing northwest.