## **Appendix D Annual Inspection and Report**

Dem-Con Landfill, Shakopee, MN SW 290 // Annual Inspection of Landfill receiving CCR		
Inspection Date & Inspector	4/2	17/16, Ben Woted
Is the landfill structure stable	ÝŅN	Comments:
Volume of CCR Managed (CY)	N	JA
Citizens Complaint Log Maintained	<b>⊘</b> N	Comments:
Employee Training Program Maintained	<b>∅</b> /N	Comments:
Were any actions taken to manage fugitive dust?	YAN	Comments:
Were any corrective measures taken during the last year?	Y/ID	Comments: