

Annual Inspection and Report

General Waste Permit # SW 620 2017 Annual Inspection of Landfill receiving CCR		
Inspection Date & Inspector	2/7/18 Bill Keegan / Jon Penheiter	
Is the landfill structure stable	<input checked="" type="radio"/> Y/N	Comments: Snow on the ground. Site Site inspected by Jon Penheiter under my direction. All looked good.
2017 Volume of CCR Managed	5,209 tons	
Citizens Complaint Log Maintained	<input checked="" type="radio"/> Y/N	Comments: No Complaints
Employee Training Program Maintained	<input checked="" type="radio"/> Y/N	Comments: No new entries in log
Were any actions taken to manage fugitive dust?	<input checked="" type="radio"/> Y/N	Comments: Cover management & application of water as needed
Were any corrective measures taken during the last year?	<input checked="" type="radio"/> Y/N	Comments:

PROFESSIONAL ENGINEER

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the State of Minnesota.

Print Name: William Keegan

Signature: 

Date 2/7/18 License # 41292



