

Annual Inspection and Report

General Waste Permit # SW 620 2018 Annual Inspection of Landfill receiving CCR		
Inspection Date & Inspector	Alan Phillips 1/24/2019	
Is the landfill structure stable	<input checked="" type="radio"/> Y <input type="radio"/> N	Comments: Slopes appear normal. No visible erosion or instability.
2018 Volume of CCR Managed	4197.93 tons	
Citizens Complaint Log Maintained	<input checked="" type="radio"/> Y <input type="radio"/> N	Comments: No complaints in 2018.
Employee Training Program Maintained	<input checked="" type="radio"/> Y <input type="radio"/> N	Comments: Employee training on 11/22/17
Were any actions taken to manage fugitive dust?	<input checked="" type="radio"/> Y <input type="radio"/> N	Comments: Water applied as necessary.
Were any corrective measures taken during the last year?	<input checked="" type="radio"/> Y <input type="radio"/> N	Comments: None

PROFESSIONAL ENGINEER

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the State of Minnesota.

Print Name: William Keegan

Signature: 

Date 2/8/19 License # 41292