

Annual Inspection and Report

General Waste Permit # SW 620 2019 Annual Inspection of Landfill receiving CCR		
Inspection Date & Inspector	1/29/2020 Alan Phillips	
Is the landfill structure stable	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Comments: No visible erosion or instability. Slopes were covered with snow at time of inspection.
2019 Volume of CCR Managed	1,639.92 tons	
Citizens Complaint Log Maintained	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Comments: No complaints in 2019
Employee Training Program Maintained	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Comments: Employee training on 12/18/2019
Were any actions taken to manage fugitive dust?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Comments: Ash loads are covered with other waste as soon as practical and safe to do so.
Were any corrective measures taken during the last year?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Comments: None

PROFESSIONAL ENGINEER

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the State of Minnesota.

Print Name: William Keegan

Signature: 

Date 2/5/2020 License # 41292