

Annual Inspection and Report

General Waste Permit # SW 620 2023 Annual Inspection of Landfill receiving CCR		
Inspection Date & Inspector	12/28/2023 Alan Phillips	
Is the landfill structure stable	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Comments: No visible erosion or instability. No slumping or cracking around slopes.
2023 Volume of CCR Managed	0 yards	
Citizens Complaint Log Maintained	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Comments: No complaints in 2023. No CCR material received in 2023.
Employee Training Program Maintained	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Comments: Employee training log is kept in binder in the scale house.
Were any actions taken to manage fugitive dust?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Comments: No CCR was received in 2023.
Were any corrective measures taken during the last year?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Comments: None

PROFESSIONAL ENGINEER

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the State of Minnesota.

Print Name: William Keegan

Signature: 

Date 8/5/24 License # 41292



Photo 1 – Industrial cells B-1 and B-2 as viewed from the southeast side, facing northwest.